

**ASSEMBLY  
BAHAR CABINET**

Ax12  
Ex12

1


|                                 |                                     |                                 |                              |                                |                             |
|---------------------------------|-------------------------------------|---------------------------------|------------------------------|--------------------------------|-----------------------------|
| <b>A</b><br>3.5X55 SCREW 40 PCS | <b>B</b><br>ALLEN WASHER 8 PCS      | <b>C</b><br>NAIL 30 PCS         | <b>D</b><br>NUT 6 PCS        | <b>E</b><br>ALLEN SCREW 32 PCS | <b>F</b><br>ALLEN           |
| <b>G</b><br>HANDLE 4 PCS        | <b>H</b><br>40X2 HANDLE SCREW 8 PCS | <b>I</b><br>HARDWARE LING 4 PCS | <b>J</b><br>SHELF PIN 25 PCS | <b>K</b><br>STOPPER            | <b>L</b><br>METAL PIN 4 PCS |

**"ACCESSORY"**





Ex16  
Fxd

2




Cx28

3



4



5

