







PR1



	B0301 x4		B0304 x10		B0317 x2		B1306 x2
----------------------------------------------------------------------------------	-------------	----------------------------------------------------------------------------------	--------------	----------------------------------------------------------------------------------	-------------	------------------------------------------------------------------------------------	-------------



Icons representing tools and materials used in the assembly process:

- Roll of tape
- Person on a ladder
- Power drill
- Hammer
- Screwdriver

